UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.	
10/721,879	11/26/2003	Harold Theodore Devor	P-6216-US	· 6009	
49444 PEARL COHE	7590 10/30/2007 EN ZEDEK LATZER, LLP		EXAMINER		
1500 BROADWAY, 12TH FLOOR			FENNEMA, ROBERT E		
NEW YORK,	NY 10036		ART UNIT PAPER NUMBER		
			2183		
			MAIL DATE	DELIVERY MODE	
			s 10/30/2007	PAPER	

Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.

		Application No.	Applicant(s)			
Office Action Summary		10/721,879	DEVOR ET AL.			
		Examiner	Art Unit			
		Robert E. Fennema	2183			
·	The MAILING DATE of this communication app	l	<u></u>			
Period fo	• •					
WHIC - Externafter - If NO - Failu Any	ORTENED STATUTORY PERIOD FOR REPLY CHEVER IS LONGER, FROM THE MAILING DATE of time may be available under the provisions of 37 CFR 1.13 SIX (6) MONTHS from the mailing date of this communication. It is period for reply is specified above, the maximum statutory period were to reply within the set or extended period for reply will, by statute, reply received by the Office later than three months after the mailing ed patent term adjustment. See 37 CFR 1.704(b).	ATE OF THIS COMMUNICATION 36(a). In no event, however, may a reply be tim will apply and will expire SIX (6) MONTHS from a cause the application to become ABANDONE	N. nely filed the mailing date of this communication. D (35 U.S.C. § 133).			
Status						
1)[🛛	1) Responsive to communication(s) filed on 10 August 2007.					
2a) <u></u> ☐	This action is <b>FINAL</b> . 2b)⊠ This action is non-final.					
3)						
	closed in accordance with the practice under E	Ex parte Quayle, 1935 C.D. 11, 45	53 O.G. 213.			
Disposit	ion of Claims					
4)⊠	4)⊠ Claim(s) <u>1,3-9,11-17,19-21 and 23-28</u> is/are pending in the application.					
	4a) Of the above claim(s) is/are withdrawn from consideration.					
•—	5) Claim(s) is/are allowed.					
•	6) Claim(s) 1, 3-9, 11-17, 19-21, and 23-28 is/are rejected.					
	Claim(s) is/are objected to.	Lead and the second				
- 8)∐	Claim(s) are subject to restriction and/o	r election requirement.				
Applicat	ion Papers					
9)[	The specification is objected to by the Examine	r.				
10) ☐ The drawing(s) filed on is/are: a) ☐ accepted or b) ☐ objected to by the Examiner.						
Applicant may not request that any objection to the drawing(s) be held in abeyance. See 37 CFR 1.85(a).						
Replacement drawing sheet(s) including the correction is required if the drawing(s) is objected to. See 37 CFR 1.121(d).						
11)	11) The oath or declaration is objected to by the Examiner. Note the attached Office Action or form PTO-152.					
Priority (	under 35 U.S.C. § 119		·			
12) Acknowledgment is made of a claim for foreign priority under 35 U.S.C. § 119(a)-(d) or (f). a) All b) Some * c) None of:						
1. Certified copies of the priority documents have been received.						
2. Certified copies of the priority documents have been received in Application No						
3. Copies of the certified copies of the priority documents have been received in this National Stage						
application from the International Bureau (PCT Rule 17.2(a)).						
* See the attached detailed Office action for a list of the certified copies not received.						
Attachmer	•		(770.440)			
	ce of References Cited (PTO-892) ce of Draftsperson's Patent Drawing Review (PTO-948)	4) Interview Summary Paper No(s)/Mail D				
3) Infor	rmation Disclosure Statement(s) (PTO/SB/08) er No(s)/Mail Date	5) Notice of Informal F 6) Other:				

Art Unit: 2183

### **DETAILED ACTION**

1. Claims 1, 3-9, 11-17, 19-21, and 23-28 are pending. Claims 1, 3-4, 8-9, 11-12, 15, 17, 19-21, and 23-24 amended as per Applicant's request.

# Claim Objections

2. Claim 1 is objected to for having insufficient antecedent basis for "the misaligned data access" in line 5. Examiner believes the line should read "... said code blocks result in a misaligned data access...", and has interpreted the claim as such for the remainder of this action.

### Claim Rejections - 35 USC § 103

- 3. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
  - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.
- 4. Claims 1, 3-7, 9, 11-15, 21, 23-26 and 28 are rejected under 35 U.S.C. 103(a) as being unpatentable over Hohensee et al. (USPN 6,064,815, herein Hohensee), in view of Angel et al. (USPN 6,643,842, herein Angel).
- 5. As per Claim 1, Hohensee teaches: A method comprising:

during translation of a code block from a first format suitable for a first computing platform to a second format suitable for a second computing platform (Column 1, Lines

Art Unit: 2183

45-47 and Column 1, Line 62-Column 2, Line 4), to detect whether execution of said code block results in the misaligned data access prior to execution of said code block (Column 3, Lines 4-9 shows the detector detecting an exceptional condition, and Column 2, Lines 61-67 show the exception to be caused by a misaligned memory reference); and

modifying said code block according to said misaligned data access (Column 8, Lines 58-66, additional code is added to the instruction stream to handle the misalignment), but fails to teach:

inserting one or more instructions in said code block.

While Hohensee teaches that there is a detection of misaligned data access prior to the execution of a code block, and a correction of said misalignment, Hohensee teaches that it is done through an exception condition detector, which is not given much more detail, and there is no indication in Hohensee that the exception condition detector is instructions inserted into the code block. Therefore, while Hohensee teaches the same end result as the claim, the way in which it is detected is presumably different. However, Angel teaches that one of the most prevalent run-time errors are relating to memory access, and that the prior art way of dealing with these issues was to insert code to monitor the performance of the code, and to provide indications when an improper access occurs (Column 1, Lines 26-37). Given that Angel teaches that this is the method used to detect memory problems (the problem also posed by Honhensee), and that it is a prior art method of detecting the problem (the time frame of the invention is the time frame which Honhensee was invented), one of ordinary skill in the art, at the

Art Unit: 2183

time the invention was made, lacking a specific way to detect the misaligned data accesses which Honhensee detects, and with Angel describing a way to do so, would have implemented Angel's method of inserting code into the software in order to implement the "detection" as described by Honhensee.

- 6. As per Claim 3, Hohensee teaches: The method of claim 1, wherein detecting comprises inserting at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3, Lines 15-17. In order to substitute code for an instruction, the location would necessarily have to have been detected).
- 7. As per Claim 4, Hohensee teaches: The method of claim 1, wherein inserting one or more instructions in of said code block comprises inserting at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3, Lines 15-17. In order to substitute code for an instruction, the location would necessarily have to have been detected).
- 8. As per Claim 5, Hohensee teaches: The method of claim 1, wherein modifying comprises adding to said code block an instruction to branch an execution of said code block to a code sequence whose execution handles the misaligned data access (Column 12, Lines 23-30. A branch to a Fixup code block is called to handle the

Art Unit: 2183

misalignment).

9. As per Claim 6, Hohensee teaches: The method of claim 1, wherein modifying comprises modifying said code block to handle misaligned data access in a subsequent execution of said code block (Column 12, Lines 23-30. A branch to a Fixup code block is called to handle the misalignment).

- 10. As per Claim 7, Hohensee teaches: The method of claim 1, further comprising translating said code block from said first format to said second format (Column 1, Line 62 Column 2, Line 4).
- 11. As per Claim 9, Hohensee teaches: An apparatus comprising:

a processor, during translation of a code block from a first format suitable for a first computing platform to a second format suitable for a second computing platform (Column 1, Lines 45-47 and Column 1, Line 62-Column 2, Line 4), in said code block to detect whether execution of said code block results in misaligned data access prior to execution (Column 3, Lines 4-9 shows the detector detecting an exceptional condition, and Column 2, Lines 61-67 show the exception to be caused by a misaligned memory reference), of said code block, and

to modify said code block according to said misaligned data access (Column 8, Lines 58-66, additional code is added to the instruction stream to handle the misalignment), but fails to teach:

Art Unit: 2183

inserting one or more instructions during translation.

While Hohensee teaches that there is a detection of misaligned data access prior to the execution of a code block, and a correction of said misalignment, Hohensee teaches that it is done through an exception condition detector, which is not given much more detail, and there is no indication in Hohensee that the exception condition detector is instructions inserted into the code block. Therefore, while Hohensee teaches the same end result as the claim, the way in which it is detected is presumably different. However, Angel teaches that one of the most prevalent run-time errors are relating to memory access, and that the prior art way of dealing with these issues was to insert code to monitor the performance of the code, and to provide indications when an improper access occurs (Column 1, Lines 26-37). Given that Angel teaches that this is the method used to detect memory problems (the problem also posed by Honhensee), and that it is a prior art method of detecting the problem (the time frame of the invention is the time frame which Honhensee was invented), one of ordinary skill in the art, at the time the invention was made, lacking a specific way to detect the misaligned data accesses which Honhensee detects, and with Angel describing a way to do so, would have implemented Angel's method of inserting code into the software in order to implement the "detection" as described by Honhensee.

12. As per Claim 11, Hohensee teaches: The apparatus of claim 9, wherein the processor is able to insert at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3,

Art Unit: 2183

Lines 15-17. In order to substitute code for an instruction, the location would necessarily have to have been detected).

- 13. As per Claim 12, Hohensee teaches: The apparatus of claim 9, wherein the processor is able to insert at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3, Lines 15-17. In order to substitute code for an instruction, the location would necessarily have to have been detected).
- 14. As per Claim 13, Hohensee teaches: The apparatus of claim 9, wherein the processor is able to add to said code block an instruction to branch an execution of said code block to a code sequence whose execution handles the misaligned data access (Column 12, Lines 23-30. A branch to a Fixup code block is called to handle the misalignment).
- 15. As per Claim 14, Hohensee teaches: The apparatus of claim 9, wherein the processor is able to modify said code block to handle misaligned data access in a subsequent execution of said code block (Column 12, Lines 23-30. A branch to a Fixup code block is called to handle the misalignment).
- 16. As per Claim 15, Hohensee teaches: The apparatus of claim 9, wherein the processor is able to, before insertion, translate said code block from said first format to

Art Unit: 2183

. . . .

said second format (Column 1, Line 62 - Column 2, Line 4).

17. As per Claim 21, Hohensee teaches: A machine-readable medium having stored thereon a set of instructions that, if executed by a machine, cause the machine to perform a method comprising:

during translation of a code block from a first format suitable for a first computing platform to a second format suitable for a second computing platform (Column 1, Lines 45-47 and Column 1, Line 62-Column 2, Line 4) detecting whether execution of said code block results in the misaligned data access prior to execution of said code block (Column 3, Lines 4-9 shows the detector detecting an exceptional condition, and Column 2, Lines 61-67 show the exception to be caused by a misaligned memory reference); and

modifying said code block according to said misaligned data access (Column 8, Lines 58-66, additional code is added to the instruction stream to handle the misalignment), but fails to teach:

inserting one or more instructions in said code block.

While Hohensee teaches that there is a detection of misaligned data access prior to the execution of a code block, and a correction of said misalignment, Hohensee teaches that it is done through an exception condition detector, which is not given much more detail, and there is no indication in Hohensee that the exception condition detector is instructions inserted into the code block. Therefore, while Hohensee teaches the same end result as the claim, the way in which it is detected is presumably different.

Art Unit: 2183

However, Angel teaches that one of the most prevalent run-time errors are relating to memory access, and that the prior art way of dealing with these issues was to insert code to monitor the performance of the code, and to provide indications when an improper access occurs (Column 1, Lines 26-37). Given that Angel teaches that this is the method used to detect memory problems (the problem also posed by Honhensee), and that it is a prior art method of detecting the problem (the time frame of the invention is the time frame which Honhensee was invented), one of ordinary skill in the art, at the time the invention was made, lacking a specific way to detect the misaligned data accesses which Honhensee detects, and with Angel describing a way to do so, would have implemented Angel's method of inserting code into the software in order to implement the "detection" as described by Honhensee.

- 18. As per Claim 23, Hohensee teaches: The machine-readable medium of claim 21, wherein the instructions that result in detecting result in insertion of at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3, Lines 15-17. In order to substitute code for an instruction, the location would necessarily have to have been detected).
- 19. As per Claim 24, Hohensee teaches: The machine-readable medium of claim 21, wherein the instructions that result in insertion result in insertion of at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3, Lines 15-17. In order to substitute

Art Unit: 2183

code for an instruction, the location would necessarily have to have been detected).

- 20. As per Claim 25, Hohensee teaches: The machine-readable medium of claim 21, wherein the instructions comprise at least part of a translator (Column 1, Lines 45-48 disclose a translator).
- 21. As per Claim 26, Hohensee teaches: The machine-readable medium of claim 21, wherein the instructions comprise at least part of an execution layer (The instructions run throughout Hohensee's invention are executed, which necessitate them being in the execution layer).
- 22. As per Claim 28, Hohensee teaches: The machine-readable medium of claim 21, wherein the instructions comprise at least part of a compiler (Column 1, Lines 45-48, where a translator is a compiler).
- 23. Claims 8, 16-17, and 19-20 are rejected under 35 U.S.C. 103(a) as being unpatentable over Hohensee and Angel.
- 24. As per Claim 8, Hohensee teaches the method of claim 1, but fails to teach:
  wherein inserting one or more instructions in said code block further comprises
  inserting one or more instructions in said code block to detect whether execution of said
  code block results in the a misaligned data access prior to execution of a code block

Art Unit: 2183

translated from a format suitable for a 32-bit based computing platform to a format suitable for a 64-bit based computing platform.

Hohensee teaches that a host processor, in an execution environment, may emulate operations performed by an emulated microprocessor, but not th sizes of the processor and the emulated processor. The Examiner is taking official notice that it is well known in the art that most computer processors operate on a number of bits that are a power of 2, for example, 8, 16, 32, 64, and 128, and that a primary difference between computer processors (of the same or similar instruction set) are a difference in the bit-size of the processors. *In re Rose*, 220 F.2d 459, 463, 105 USPQ 237, 240 (CCPA 1955) teaches that it is within the skill of one of ordinary skill in the art to change size, so whether the emulation required was from 8 to 16 bits, 16 to 32 bits, or 32 to 64 bits is irrelevant to one of ordinary skill in the art. Therefore, one of ordinary skill in the art would have been able to make use of Hohensees invention, and apply it to a 64-bit processor running a 32-bit program.

25. As per Claim 16, Hohensee teaches the apparatus of claim 9, but fails to teach: wherein the first computing platform is a 32-bit based computing platform and the second computer architecture is a 64-bit based computing platform. Hohensee teaches that a host processor, in an execution environment, may emulate operations performed by an emulated microprocessor, but not the sizes of the processor and the emulated processor. The Examiner is taking official notice that it is well known in the art that most computer processors operate on a number of bits that are a power of 2, for example, 8,

Art Unit: 2183

16, 32, 64, and 128, and that a primary difference between computer processors (of the same or similar instruction set) are a difference in the bit-size of the processors. *In re Rose*, 220 F.2d 459, 463, 105 USPQ 237, 240 (CCPA 1955) teaches that it is within the skill of one of ordinary skill in the art to change size, so whether the emulation required was from 8 to 16 bits, 16 to 32 bits, or 32 to 64 bits is irrelevant to one of ordinary skill in the art. Therefore, one of ordinary skill in the art would have been able to make use of Hohensee's invention, and apply it to a 64-bit processor running a 32-bit program.

26. As per Claim 17, Hohensee teaches: A computing platform comprising:

a processor, during translation of a code block from a first format suitable for a first computing platform to a second format suitable for a second computing platform (Column 1, Lines 45-47 and Column 1, Line 62-Column 2, Line 4), in said code block to detect whether execution of said code block results in misaligned data access prior to execution (Column 3, Lines 4-9 shows the detector detecting an exceptional condition, and Column 2, Lines 61-67 show the exception to be caused by a misaligned memory reference) of said code block, and

to modify said code block according to said misaligned data access (Column 8, Lines 58-66, additional code is added to the instruction stream to handle the misalignment); and

a dynamic random access memory operably associated with said processor to store at least a portion of said code block (Figure 1 discloses a memory, but Hohensee does not explicitly teach the memory being a dynamic random access memory (herein

Art Unit: 2183

DRAM). However, the Examiner is taking official notice that using a DRAM for computer memory is well known in the art, due to its cheap cost and widespread use, which would have motivated one of ordinary skill in the art to utilize a DRAM in Hohensee's invention), but fails to teach:

inserting one or more instructions.

While Hohensee teaches that there is a detection of misaligned data access prior to the execution of a code block, and a correction of said misalignment, Hohensee teaches that it is done through an exception condition detector, which is not given much more detail, and there is no indication in Hohensee that the exception condition detector is instructions inserted into the code block. Therefore, while Hohensee teaches the same end result as the claim, the way in which it is detected is presumably different. However, Angel teaches that one of the most prevalent run-time errors are relating to memory access, and that the prior art way of dealing with these issues was to insert code to monitor the performance of the code, and to provide indications when an improper access occurs (Column 1, Lines 26-37). Given that Angel teaches that this is the method used to detect memory problems (the problem also posed by Honhensee), and that it is a prior art method of detecting the problem (the time frame of the invention is the time frame which Honhensee was invented), one of ordinary skill in the art, at the time the invention was made, lacking a specific way to detect the misaligned data accesses which Honhensee detects, and with Angel describing a way to do so, would have implemented Angel's method of inserting code into the software in order to

Page 14

Application/Control Number: 10/721,879

Art Unit: 2183

implement the "detection" as described by Honhensee.

- 27. As per Claim 19, Hohensee teaches: The apparatus of claim 17, wherein the processor is able to insert at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3, Lines 15-17. In order to substitute code for an instruction, the location would necessarily have to have been detected).
- 28. As per Claim 20, Hohensee teaches: The apparatus of claim 17, wherein the processor is able to insert at least one instruction in said code block to detect a location of an instruction whose execution results in the misaligned data access (Column 3, Lines 15-17. In order to substitute code for an instruction, the location would necessarily have to have been detected).
- 29. Claim 27 is rejected under 35 U.S.C. 103(a) as being unpatentable over Hohensee, in view of Drongowski.
- 30. As per Claim 27, Hohensee teaches: The machine-readable medium of claim 21, wherein the instructions comprise at least part of an operating system. While Hohensee does not explicitly disclose an operating system, it would have been very obvious to one of ordinary skill in the art to be able to make use of misalignment correction capabilities on the operating-system level, so that all programs and programmers can make use of

Art Unit: 2183

it, as well as the fact that operating systems are extremely common on most computing systems. Drongowski teaches an example of an operating system (The Alpha Linux) that makes use of commands to fix alignment problems (Section 2.7), and explains the problems misalignment can cause. Therefore, it would have been obvious to one of ordinary skill in the art at the time the invention was made to allow an operating system to run these instructions and make use of Hohensee's invention.

# Response to Arguments

31. Applicant's arguments with respect to the claims have been considered but are moot in view of the new ground(s) of rejection.

### **Conclusion**

- 32. The prior art made of record and not relied upon is considered pertinent to applicant's disclosure as follows. Applicant is reminded that in amending in response to a rejection of claims, the patentable novelty must be clearly shown in view of the state of the art disclosed by the references cited and the objections made. Applicant must also show how the amendments avoid such references and objections. See 37 CFR § 1.111(c).
- 33. Blasciak et al. (USPN 5,265,254) teaches a method of inserting code markers into a code block to provide debugging support to a user.

Art Unit: 2183

34. Hastings (USPN 5,193,180) teaches a method of inserting code into a code block to monitor memory access.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Robert E. Fennema whose telephone number is (571) 272-2748. The examiner can normally be reached on Monday-Friday, 8:45-6:15.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Eddie Chan can be reached on (571) 272-4162. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

Robert E Fennema

Examiner

Art Unit 2183

RF

RICHARD L. ELLIS

Page 17

Application/Control Number: 10/721,879

Art Unit: 2183